



Picture 1 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Clay-lined manure pit at the main barn, scheduled for expansion in July 2013.



Picture 2 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Open feed lot located southwest of the main barn.



Picture 3 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Animal pen located outside the main barn.



Picture 4 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Sawdust bedding storage containers.



Picture 5 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Silage breach from the wall of an older concrete bunker.



Picture 6 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
View of a silage storage bunker with a new concrete wall.



Picture 7 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Location of channelized runoff from the silage area (looking north).



Picture 8 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Location where runoff from the silage area enters a drainage channel (looking south).



Picture 9 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Leachate leak from an older concrete bunker.



Picture 10 – Meadowbrook Acres, Inc., 1238 Lake Rd., Milton, VT – 05/15/13
Location where the leachate leak (in picture #9) flows south into a grassy drainage area.